

## Inspector Secrets - Pabco HO-25 Roofing

Pabco HO-25 roofing material, short for, Horizon 25, was a 25 year warranted three tab, laminated shingle developed by Pabco in Tacoma. It was used widely in many areas until it was discontinued in 1996.

Early on, the product exhibited superficial cracking and crazing as well as lifting and curling on the corners. In 2003 a class action suit was filed against Pabco based on complaints of failure and the aforementioned cracking. For more information about the suit, go to [www.HO25Settlement.com](http://www.HO25Settlement.com). The photos below should help in identification of the product.



On the left, a typical 3 Tab Shingle


On the right, HO-25. Note the shadow lines and dimensional appearance as well as the cracking.



Want to know more? Have other inspection questions?  
Contact us at 360.459.1632 or  
[cameohomeinspection@comcast.net](mailto:cameohomeinspection@comcast.net)



The Most Qualified Inspector in  
Thurston County  
*Check out our resource list at*  
[www.cameohis.com](http://www.cameohis.com)



Get the free mobile app for your phone:  
<http://gettag.mobi>